

Survey Reference	B-50239
Client	Regal Theatre
Lead Surveyor	Tony Osborne
Assistant Surveyor	N/A
Start Date	13 June 2012
Completion Date	26 June 2012
Reviewed By	Jon House

REFURBISHMENT ASBESTOS SURVEY REPORT

BUILDING SURVEYED

New Lift Area Only
Regal Theatre
The Avenue
Minehead
TA24 5UQ



This document is not to be used by a third party without the express permission of Shield Environmental Services Ltd (Surveying Division). No liability to anyone else is accepted. Should you not act upon specific reasonable advice contained within this report, no responsibility is accepted for the consequences.

No liability to anyone else is accepted. Should you not act upon specific reasonable advice contained within this report, no responsibility is accepted for the consequences. This inspection report shall not be reproduced except in full without the approval of the inspection body and the client.

Shield Environmental Services Ltd (Surveying Division) wish to advise our client/s that no obligation (actual, assumed or otherwise) maybe placed upon the client, for further work related to the recommendations from this report.



Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ

Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2010 Shield Environmental Services Ltd



TABLE OF CONTENTS

- 1: - EXECUTIVE SUMMARY
- 2: - INTRODUCTION
- 3: - GENERAL SITE INFORMATION
- 4: - CONCLUSIONS AND ACTIONS
- 5: - SURVEY METHOD
- 6: - GENERAL COMMENTS
- 7: - APPENDIX 1 – REGISTER OF ACMs
PAGE 13 - 15
- 8: - APPENDIX 2 – REGISTER OF NON-ACMs
PAGE 17 - 19
- 9: - APPENDIX 3 – PLANS
PLAN 1 – GROUND FLOOR
PLAN 2 – FIRST FLOOR
PLAN 3 – SECOND FLOOR
- 10: - APPENDIX 4 – BULK MATERIAL ANALYSIS REPORT
3 CERTIFICATES IN TOTAL



212

Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ

Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2010 Shield Environmental Services Ltd



1: EXECUTIVE SUMMARY

A Refurbishment Asbestos Survey, carried out in accordance with in-house asbestos surveying procedures and HSE guidance document HSG 264 was conducted at New Lift Area Regal Theatre, The Avenue, Minehead, TA24 5UQ.

The survey was carried out by Shield Environmental Services Ltd (Surveying Division) on behalf of Regal Theatre on 13th June 2012.

The purpose of this survey was to locate, as far as reasonably practicable, the presence and extent of all suspected Asbestos Containing Materials (ACMs) in the building(s) prior to planned refurbishment activities.

During the survey 18 samples of suspected ACMs were taken for analysis, ACMs were found or presumed in the form of:

- Textured Coating
- Insulation Board
- Roofing Felt



212

Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ

Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2010 Shield Environmental Services Ltd



1: EXECUTIVE SUMMARY (continued)

Inaccessible areas encountered during the time of the survey, for which no information was obtained:

- None

REPORT REVIEWED BY - Jon House



SIGNED -

Please note Shield Environmental Services Ltd (Surveying Division) cannot be held responsible for the way in which the Client may interpret or act upon the results of this report.



212

Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ

Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2010 Shield Environmental Services Ltd



2: INTRODUCTION

Shield Environmental Services Ltd (Surveying Division) has been instructed to carry out an asbestos survey by;

Regal Theatre (James Scott)

To ascertain the presence of any asbestos containing materials at;
New Lift Area, Regal Theatre, The Avenue, Minehead, TA24 5UQ

Description of Site

The site consists of a theatre

Survey Type

The nature of the survey is a Refurbishment Asbestos Survey as detailed in HSE publication HSG 264 Asbestos: The survey guide. The purpose of the survey is to locate and describe, as far as reasonably practicable, all ACMs in the building(s) and may involve destructive inspection, as necessary, to gain access to all areas, including those difficult to reach. A full sampling programme is undertaken to identify possible ACMs and estimates of volume and surface area made. The survey is designed to be used as a guide for tendering the removal of ACMs from the building(s) prior to refurbishment.

This report presents the findings of the survey and analysis reports of any bulk samples taken.

Floor Plans

Where provided floor plans should be regarded as sketch-plans and for identification purposes only. They are intended to provide a visual appreciation of the buildings surveyed, showing locations of suspected ACMs, areas of no access and where samples were taken.



212

Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ

Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2010 Shield Environmental Services Ltd



3: GENERAL SITE INFORMATION

SURVEY CONSULTANTS	-	Shield Environmental Services Ltd. (Surveying Division) Shield House, Caxton Business Park, Crown Way, Warmley, Bristol, BS30 8XJ
SURVEY CONDUCTED BY	-	Tony Osborne
CLIENT	-	Regal Theatre The Avenue Minehead TA24 5UQ
CLIENT CONTACT	-	James Scott
SITE ADDRESS	-	Regal Theatre The Avenue Minehead TA24 5UQ
SURVEY DATE(S)	-	13 th June 2012
REPORT DATE	-	21 st June 2012
REPORT TYPED BY	-	Emily Hughes
REPORT ISSUED	-	26 June 2012
REPORT REFERENCE	-	B-50239



Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ

Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2010 Shield Environmental Services Ltd



3: GENERAL SITE INFORMATION (continued)

- Areas Included in the Survey:
 - New lift area only of Regal Theatre, The Avenue, Minehead, TA24 5UQ were included in the survey.
- Agreed Exclusions and Inaccessible Areas:
 - All other areas of Regal Theatre, The Avenue, Minehead, TA24 5UQ were excluded from the survey.
- Inaccessible areas encountered during the time of the survey, for which no information was obtained:
 - None
- Survey Methodology:
 - In-house asbestos surveying procedures and HSE guidance document HSG 264.
- Survey Type
 - Refurbishment Survey as defined in HSE guidance document HSG 264.
- Agreed Variations or Deviations from the standard HSG 264 method:
 - None
- Areas Excluded from the Survey (Areas outside of ownership and control):
 - None



212

Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ

Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2010 Shield Environmental Services Ltd



4: CONCLUSIONS AND ACTIONS

Room No	Asbestos Containing Product	Recommended Actions	Urgency
201 - New lift Area - Ceiling	Textured Coating	Remove If Affected By Proposed Refurbishment Works	Low
201 - New lift Area – Wall	Textured Coating	Remove If Affected By Proposed Refurbishment Works	Low
201 - New lift Area – Wall	Insulating Board Panels	Remove If Affected By Proposed Refurbishment Works	Low
101 - New lift Area - Ceiling	Textured Coating	Remove If Affected By Proposed Refurbishment Works	Low
101 - New lift Area - Wall	Textured Coating	Remove If Affected By Proposed Refurbishment Works	Low
001 - New lift Area - Ceiling	Textured Coating	Remove If Affected By Proposed Refurbishment Works	Low
201 - New lift Area – Wall	Insulating Board Panels	Remove If Affected By Proposed Refurbishment Works	Low
External	Bitumen Roofing Felt	Remove If Affected By Proposed Refurbishment Works	Low



212

Shield Environmental Services Ltd
 Surveying Division
 Shield House
 Caxton Business Park
 Crown Way, Warmley
 Bristol BS30 8XJ

Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2010 Shield Environmental Services Ltd



5: SURVEY METHOD

The survey is conducted in accordance with our in-house asbestos surveying procedures and HSE guidance document HSG 264. Where appropriate, bulk samples of suspected ACMs are taken from the property.

Representative samples are also taken of any materials that may be confused with ACMs. Sampling location stickers, bearing the individual samples unique identification number, are applied to all sample points where practicable, for future reference.

Products that are very unlikely to contain asbestos are not sampled (e.g. wall paper, plasterboard, chipboard, wood etc).

All samples taken are sent to a UKAS Accredited Laboratory for analysis by polarised light microscopy (PLM) as per the method prescribed in HSG248 Asbestos: The analysts' guide for sampling, analysis and clearance procedures. Completed bulk sample analysis test reports for all samples taken are appended for client review.

A Survey Report Form (SRF) is completed for each suspect sample taken, for materials strongly presumed to contain asbestos (i.e. materials visually similar to positively identified ACMs) and for areas presumed to contain asbestos (i.e. areas where no access could be gained at the time of the survey and non-accessed items of (electrical) equipment and plant.

Each SRF contains a colour photograph, individual material risk assessment scores (as prescribed under HSG 264), management recommendations and general observations / comments (where appropriate).

The SRFs are combined together to form a site-specific asbestos register (see Appendix 1).



212

Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ

Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2010 Shield Environmental Services Ltd



6: GENERAL COMMENTS

This report only relates to the situation on the day(s) of the inspection and cannot take into account subsequent changes in circumstances. Materials were only sampled where the surveyor considered there was a high probability that they may contain asbestos. This report contains findings based upon visual inspection and results of laboratory analysis.

During the course of the survey all reasonable efforts were made to identify the presence of asbestos containing materials within the surveyed areas however, asbestos containing materials are sometimes concealed within the fabric of a building or within sealed building voids, so it is not always possible to regard the findings of any survey as being definitive. Therefore, it must always remain a possibility that further asbestos containing materials may be found during any alteration or refurbishment works.

Where areas have been identified as inaccessible within the report, it indicates that the area specified was not accessible to the surveyor at the time of the inspection, either because such areas were locked and despite requests for access to be arranged none was, or to gain entry would require an unreasonable degree of dismantling to the structure of the building. The client is therefore advised to the possibility of there being asbestos containing materials in such areas.

Manufactured products containing asbestos have been extremely diverse. Therefore, responsibility cannot be accepted for any consequential loss or damage resulting from non-recognition of a material that is later established as having an asbestos content.

Figures quoted in the asbestos register detailing the extent of ACMs are approximate based on visual inspection on the day of the survey and should be used as a guide only.

No responsibility can be taken for any misinterpretation of this report by third parties.

Please Note:

The content of this report should only be used for guidance in support of refurbishment works requiring the removal of ACMs and not as an actual specification of tender.



212

Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ

Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2010 Shield Environmental Services Ltd



6: GENERAL COMMENTS (continued)

The survey was limited to those areas accessed at the time of the Survey.

No responsibility will be accepted for the presence of asbestos in voids (under floor, or behind wall or ceiling) or pipework ducts other than those opened up during the survey.

We have not reported on concealed spaces, which may exist within the fabric of the building where the extent and presence of these is not evident due to inaccessibility or insufficient knowledge of the structure at the time of the survey.

Representative bulk samples have been taken from all materials, which upon visual inspection appeared likely to contain asbestos.

Unless otherwise stated pipe work insulation and heating plant was not inspected in entirety. Representative samples were taken at random intervals where suspect material was observed. The scope of the works did not permit complete exposure and assessment of all pipework and heating plant.

Due to the nature and variety of asbestos uses in building construction and the complex nature of some buildings, especially where modified over the years, it is possible that some ACMs may not have been identified in the survey. Where major refurbishment is to follow a Refurbishment Survey, it would be prudent in any contract to allow a contingency sum to provide for such possibility.

Manufactured products containing asbestos have been extremely diverse, therefore responsibility cannot be accepted for any consequential loss or damage resulting from non-recognition of a material which is later established as having an asbestos content. Certain 'Artex' type textured coatings and decorative plasters may contain very small quantities of asbestos. In situ, these coatings are often composed of different batches of product or may have been repaired / patched at different times. It is, therefore, possible that any 'Artex' samples taken may not be representative of the entire coating. Recent research suggests that in some cases, the fibres may have diameters below 0.1 um. These may not be visible by the optical microscopy method described in HSE publications HSG248.



212

Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ

Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2010 Shield Environmental Services Ltd



7: REGISTER OF ASBESTOS CONTAINING MATERIALS



Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ


Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2007 Shield Environmental Services Ltd



Ref	Sample No	Floor	Location	Description	Access.	(A) Product Type	(B) Condition	(C) Surface Treatment	(D) Asbestos Type	Material Assessment Score (A + B + C + D)	Priority	Photo
1	B-50239/001	Second Floor	201 New lift Area - Ceiling	Textured Coating	Low	1	0	1	1	3	Low	
Quantity		ID	Recommendations	Comments								
5m²		AD	Remove If Affected Bu Proposed Refurbishment Works	Work with this material to be carried out in accordance with The Control of Asbestos Regulations (2012.). All waste to be disposed of in accordance with the Hazardous Waste Regulations 2005.								

Ref	Sample No	Floor	Location	Description	Access.	(A) Product Type	(B) Condition	(C) Surface Treatment	(D) Asbestos Type	Material Assessment Score (A + B + C + D)	Priority	Photo	
2	B-50239/002	Second Floor	201 New lift Area – Wall Adjacent Door	Textured Coating	High	1	1	0	1	3	Low		
Quantity		ID	Recommendations	Comments									
5m²		AD	Remove If Affected Bu Proposed Refurbishment Works	Work with this material to be carried out in accordance with The Control of Asbestos Regulations (2012.). All waste to be disposed of in accordance with the Hazardous Waste Regulations 2005.									

Ref	Sample No	Floor	Location	Description	Access.	(A) Product Type	(B) Condition	(C) Surface Treatment	(D) Asbestos Type	Material Assessment Score (A + B + C + D)	Priority	Photo	
6	B-50239/006	Second Floor	201 New lift Area – Wall Adjacent Door Behind Plasterboard & Wood Panels	Insulation Board Panels	Low	2	1	1	1	5	Low		
Quantity		ID	Recommendations	Comments									
6m ² Visible		AD	Remove If Affected Bu Proposed Refurbishment Works	Work with this material to be carried out in accordance with The Control of Asbestos Regulations (2012.). All waste to be disposed of in accordance with the Hazardous Waste Regulations 2005.									

Material Assessment Algorithm**A: Product Type:**

1 Asbestos Reinforced composites (plastics, resins, mastics, roofing felt, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc)
 2 AIB, millboards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper etc.
 3 Thermal insulation (eg pipe and boiler lagging), sprayed asbestos, loose asbestos, asbestos mattresses and packing.

Priority Score (A+B+C+D) = (1-6 Low) (7-9 Medium) (≥10 High)

B: Extent of Damage / Deterioration:

0 Good condition: no visible damage.

1 Low damage: a few scratches or surface marks, broken edges on boards, tiles etc

2 Medium Damage: significant breakage of materials or several small areas where material has been damaged

3 High Damage or delamination of materials, sprays and thermal insulation. Visible asbestos Debris

C: Surface Treatment:

0 Composite materials containing asbestos: reinforced plastics, resins, vinyl tiles

1 Enclosed sprays and lagging, AIB (with exposed face painted or encapsulated) asbestos cement sheets etc

2 Unsealed AIB or encapsulated lagging and sprays

3 Unsealed lagging and sprays

D: Asbestos Type:


1 Chrysotile

2 Amphibole asbestos excluding crocidolite

3 Crocidolite

Ref	Sample No	Floor	Location	Description	Access.	(A) Product Type	(B) Condition	(C) Surface Treatment	(D) Asbestos Type	Material Assessment Score (A + B + C + D)	Priority	Photo
8	B-50239/008	First Floor	101 New lift Area - Ceiling	Textured Coating	Low	1	0	0	1	2	Low	
Quantity		ID	Recommendations	Comments								
6m²		AD	Remove If Affected Bu Proposed Refurbishment Works	Work with this material to be carried out in accordance with The Control of Asbestos Regulations (2012.). All waste to be disposed of in accordance with the Hazardous Waste Regulations 2005.								

Ref	Sample No	Floor	Location	Description	Access.	(A) Product Type	(B) Condition	(C) Surface Treatment	(D) Asbestos Type	Material Assessment Score (A + B + C + D)	Priority	Photo	
9	B-50239/009	First Floor	101 New lift Area - Wall	Textured Coating	High	1	0	0	1	2	Low		
Quantity		ID	Recommendations	Comments									
8m²		AD	Remove If Affected Bu Proposed Refurbishment Works	Work with this material to be carried out in accordance with The Control of Asbestos Regulations (2012.). All waste to be disposed of in accordance with the Hazardous Waste Regulations 2005.									

Ref	Sample No	Floor	Location	Description	Access.	(A) Product Type	(B) Condition	(C) Surface Treatment	(D) Asbestos Type	Material Assessment Score (A + B + C + D)	Priority	Photo	
11	B-50239/011	Ground Floor	001 New lift Area – Ceiling, Beams & Timber Strips	Textured Coating	Low	1	0	0	1	2	Low		
Quantity		ID	Recommendations	Comments									
8m²		AD	Remove If Affected Bu Proposed Refurbishment Works	Work with this material to be carried out in accordance with The Control of Asbestos Regulations (2012.). All waste to be disposed of in accordance with the Hazardous Waste Regulations 2005.									

Material Assessment Algorithm**A: Product Type:**

1 Asbestos Reinforced composites (plastics, resins, mastics, roofing felt, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc)
 2 AIB, millboards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper etc.
 3 Thermal insulation (eg pipe and boiler lagging), sprayed asbestos, loose asbestos, asbestos mattresses and packing.

Priority Score (A+B+C+D) = (1-6 Low) (7-9 Medium) (≥10 High)

B: Extent of Damage / Deterioration:

0 Good condition: no visible damage.

1 Low damage: a few scratches or surface marks, broken edges on boards, tiles etc

2 Medium Damage: significant breakage of materials or several small areas where material has been damaged

3 High Damage or delamination of materials, sprays and thermal insulation. Visible asbestos Debris

C: Surface Treatment:

0 Composite materials containing asbestos: reinforced plastics, resins, vinyl tiles

1 Enclosed sprays and lagging, AIB (with exposed face painted or encapsulated) asbestos cement sheets etc

2 Unsealed AIB or encapsulated lagging and sprays

3 Unsealed lagging and sprays

D: Asbestos Type:

1 Chrysotile

2 Amphibole asbestos excluding crocidolite

3 Crocidolite

Ref	Sample No	Floor	Location	Description	Access.	(A) Product Type	(B) Condition	(C) Surface Treatment	(D) Asbestos Type	Material Assessment Score (A + B + C + D)	Priority	Photo
14	B-50239/014	Second Floor	201 New lift Area – Wall Behind Plasterboard	Panels	Low	2	0	1	1	4	Low	
Quantity		ID	Recommendations	Comments								
10m²		AD	Remove If Affected Bu Proposed Refurbishment Works	Work with this material to be carried out in accordance with The Control of Asbestos Regulations (2012.). All waste to be disposed of in accordance with the Hazardous Waste Regulations 2005.								

Ref	Sample No	Floor	Location	Description	Access.	(A) Product Type	(B) Condition	(C) Surface Treatment	(D) Asbestos Type	Material Assessment Score (A + B + C + D)	Priority	Photo	
17	B-50239/017	External	Front Entrance Roof	Roofing Felt	Low	1	0	0	1	2	Low		
Quantity		ID	Recommendations	Comments									
10m²		AD	Remove If Affected Bu Proposed Refurbishment Works	Work with this material to be carried out in accordance with The Control of Asbestos Regulations (2012.). All waste to be disposed of in accordance with the Hazardous Waste Regulations 2005.									

Material Assessment Algorithm**A: Product Type:**

1 Asbestos Reinforced composites (plastics, resins, mastics, roofing felt, vinyl floor tiles, semi-rigid paints or decorative finishes, asbestos cement etc)
 2 AIB, millboards, other low density insulation boards, asbestos textiles, gaskets, ropes and woven textiles, asbestos paper etc.
 3 Thermal insulation (eg pipe and boiler lagging), sprayed asbestos, loose asbestos, asbestos mattresses and packing.

Priority Score (A+B+C+D) = (1-6 Low) (7-9 Medium) (≥10 High)

B: Extent of Damage / Deterioration:

0 Good condition: no visible damage.

1 Low damage: a few scratches or surface marks, broken edges on boards, tiles etc

2 Medium Damage: significant breakage of materials or several small areas where material has been damaged

3 High Damage or delamination of materials, sprays and thermal insulation. Visible asbestos Debris

C: Surface Treatment:

0 Composite materials containing asbestos: reinforced plastics, resins, vinyl tiles

1 Enclosed sprays and lagging, AIB (with exposed face painted or encapsulated) asbestos cement sheets etc

2 Unsealed AIB or encapsulated lagging and sprays

3 Unsealed lagging and sprays

D: Asbestos Type:

1 Chrysotile

2 Amphibole asbestos excluding crocidolite

3 Crocidolite

8: REGISTER OF NON-ASBESTOS CONTAINING MATERIALS




212

Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ


Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2010 Shield Environmental Services Ltd



Ref	Sample No	Floor	Location	Description	Photo
3	B-50239/003	Second Floor	201 New lift Area - Door	Putty To Door Window	
Quantity		ID	Comments		
2 lm		NAD			

Ref	Sample No	Floor	Location	Description	Photo
4	B-50239/004	Second Floor	201 New lift Area – Floor Void	Debris	
Quantity		ID	Comments		
5m²		NAD			


Ref	Sample No	Floor	Location	Description	Photo
5	B-50239/005	Second Floor	201 New lift Area – Ceiling Adjacent Door	Textured Coating	
Quantity		ID	Comments		
8m²		NAD			

Ref	Sample No	Floor	Location	Description	Photo
7	B-50239/007	Second Floor	201 New lift Area – Wall Cavity	Residue	
Quantity		ID	Comments		
Throughout		NAD			

Ref	Sample No	Floor	Location	Description	Photo
10	B-50239/010	First Floor	101 New lift Area – Wall Cavity	Residue	
Quantity		ID	Comments		
Throughout		NAD			

Ref	Sample No	Floor	Location	Description	Photo
12	B-50239/012	Ground Floor	001 New lift Area - Floor	Vinyl Flooring & Bitumen Adhesive	
Quantity		ID	Comments		
8m²		NAD			

Ref	Sample No	Floor	Location	Description	Photo
13	B-50239/013	Ground Floor	001 New lift Area – Wall Cavity	Residue	
Quantity		ID	Comments		
Throughout		NAD			

Ref	Sample No	Floor	Location	Description	Photo
15	B-50239/015	First Floor	101 New lift Area – Wall Cavity	Residue	
Quantity		ID	Comments		
Throughout		NAD			

Ref	Sample No	Floor	Location	Description	Photo
16	B-50239/016	External	External – Wall Cavity	Residue	
Quantity		ID	Comments		
Throughout		NAD			

Ref	Sample No	Floor	Location	Description	Photo
18	B-50239/018	Ground Floor	001 New lift Area – Wall Cavity	Residue	
Quantity		ID	Comments		
Throughout		NAD			

9: PLANS



212

Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ


Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2007 Shield Environmental Services Ltd





THIS PLAN SHOULD BE
READ IN CONJUNCTION
WITH THE MAIN BODY OF
THE REPORT AND
INDIVIDUAL SRF'S




Floor Level / Area:	Ground Floor
Plan No:	1 of 3

KEY

SRFs Positive ACM	
SRFs None Asbestos	
No access or limited access gained	


Asbestos Containing Materials (ACMs) presumed, strongly presumed or identified as containing asbestos and for areas where no access has been gained indicated using red text.

Materials presumed, strongly presumed or identified as not containing asbestos indicated using black text.



THIS PLAN SHOULD BE READ IN CONJUNCTION WITH THE MAIN BODY OF THE REPORT AND INDIVIDUAL SRF'S

Floor Level / Area:	First Floor
Plan No:	2 of 3
KEY	
SRFs Positive ACM	
SRFs None Asbestos	
SRFs No access or limited access gained	
Asbestos Containing Materials (ACMs) presumed, strongly presumed or identified as <u>containing asbestos</u> and for areas where no access has been gained indicated using red text.	
Materials presumed, strongly presumed or identified as <u>not containing asbestos</u> indicated using black text.	



THIS PLAN SHOULD BE
READ IN CONJUNCTION
WITH THE MAIN BODY OF
THE REPORT AND
INDIVIDUAL SRF'S

Floor Level / Area:	Second Floor
Plan No:	3 of 3
KEY	
SRFs Positive ACM	
SRFs None Asbestos	
SRFs No access or limited access gained	
Asbestos Containing Materials (ACMs) presumed, strongly presumed or identified as <u>containing asbestos</u> and for areas where no access has been gained indicated using red text.	
Materials presumed, strongly presumed or identified as <u>not containing asbestos</u> indicated using black text.	

10: BULK MATERIAL ANALYSIS REPORT



212

Shield Environmental Services Ltd
Surveying Division
Shield House
Caxton Business Park
Crown Way, Warmley
Bristol BS30 8XJ

Tel 0117 960 6366
Fax 0117 960 5583
Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2007 Shield Environmental Services Ltd





ENVIROCHEM

Analytical Laboratories Ltd.

12 The Gardens

Broadcut, Fareham

Hampshire

PO16 8SS



Tel: (01329) 287777

Fax: (01329) 287755

www.envirochem.co.uk

office@envirochem.co.uk

Our Ref: 1205077 FI 18

Your Ref:

Date: 18 June 2012

ASBESTOS FIBRE IDENTIFICATION REPORT

Client: Shield Environmental Services Ltd (Bristol)
 Shield House, Caxton Business Park, Crown Way, Warmley, Bristol, BS30 8XJ
Site address: Regal Theatre, Minehead, The Avenue, TA24 5UQ
Sampled by: Client
Date sampled/received: 15 June 2012
Date analysed: 18 June 2012
Analyst/s: E. Kowalczyk Pariyar

ANALYTICAL PROCEDURE

Fibre identification was carried out in accordance with the documented 'in-house' methods based on the HSE Guidance Note HSG 248. These employed stereo microscopy, polarized microscopy and dispersion staining techniques.

RESULTS

Sample no.	Sample ref.	Location	Asbestos detected	Asbestos type
B-50239/001	1205077 1FI	Coating to solid ceiling	Yes	Chrysotile
B-50239/002	1205077 2FI	Coating to wall (solid)	Yes	Chrysotile
B-50239/003	1205077 3FI	Putty to door	No	
B-50239/004	1205077 4FI	Residues beneath floor boards on 2nd floor	No	
B-50239/005	1205077 5FI	Textured coating to ceiling in landing	No	
B-50239/006	1205077 6FI	Panel to wall	Yes	Chrysotile

NOTES:

- 1-Sample(s) were examined for the presence of 6 types of asbestos fibre: crocidolite (blue), amosite (brown), chrysotile (white), anthophyllite, actinolite, and tremolite.
- 2-Samples collected by the client are evaluated using information provided by the client. For samples collected by the client the date of receipt is deemed to be the same as the date sampled.
- 3-Envirochem is a UKAS accredited laboratory for sampling and identification of asbestos containing materials.
- 4-Comments, observations and opinions are outside the scope of UKAS accreditation.
- 5-The analytical method in the HSG248 does not quantify the amount of asbestos present, therefore UKAS accreditation does not permit quantification.
- 6-If, during fibre identification, only 1 or 2 fibres are seen and identified as asbestos, then the term 'trace asbestos identified' is used.

SIGNATURE:

PRINT NAME:

Ewelina Kowalczyk Pariyar

Reg. No.2378228 England. Registered Office: Envirochem, 12 The Gardens, Broadcut, Fareham, Hampshire. PO16 8SS.

Page 1 of 3



212

Shield Environmental Services Ltd
 Surveying Division
 Shield House
 Caxton Business Park
 Crown Way, Warmley
 Bristol BS30 8XJ

Tel 0117 960 6366
 Fax 0117 960 5583
 Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2007 Shield Environmental Services Ltd





ENVIROCHEM

Analytical Laboratories Ltd.

12 The Gardens

Broadcut, Fareham

Hampshire

PO16 8SS



Tel: (01329) 287777

Fax: (01329) 287755

www.envirochem.co.uk

office@envirochem.co.uk

Our Ref: 1205077 FI 18

Your Ref:

Date: 18 June 2012

ASBESTOS FIBRE IDENTIFICATION REPORT

Client: Shield Environmental Services Ltd (Bristol)
 Shield House, Caxton Business Park, Crown Way, Warmley, Bristol, BS30 8XJ

Site address: Regal Theatre, Minehead, The Avenue, TA24 5UQ

Sampled by: Client

Date sampled/received: 15 June 2012

Date analysed: 18 June 2012

Analyst/s: E. Kowalczyk Pariyar

ANALYTICAL PROCEDURE

Fibre identification was carried out in accordance with the documented 'in-house' methods based on the HSE Guidance Note HSG 248. These employed stereo microscopy, polarized microscopy and dispersion staining techniques.

B-50239/007	1205077 7FI	Residues to wall	No	
B-50239/008	1205077 8FI	Textured coating to solid ceiling	Yes	Chrysotile
B-50239/009	1205077 9FI	Textured coating to solid wall	Yes	Chrysotile
B-50239/010	1205077 10FI	Residues to solid wall behind textured coating	No	
B-50239/011	1205077 11FI	Textured coating to ceiling and beams	Yes	Chrysotile
B-50239/012	1205077 12FI	Flooring and adhesive	No	
B-50239/013	1205077 13FI	Residues within solid wall	No	

NOTES:

- 1-Sample(s) were examined for the presence of 6 types of asbestos fibre: crocidolite (blue), amosite (brown), chrysotile (white), anthophyllite, actinolite, and tremolite.
- 2-Samples collected by the client are evaluated using information provided by the client. For samples collected by the client the date of receipt is deemed to be the same as the date sampled.
- 3-Envirochem is a UKAS accredited laboratory for sampling and identification of asbestos containing materials.
- 4-Comments, observations and opinions are outside the scope of UKAS accreditation.
- 5-The analytical method in the HSG248 does not quantify the amount of asbestos present, therefore UKAS accreditation does not permit quantification.
- 6-If, during fibre identification, only 1 or 2 fibres are seen and identified as asbestos, then the term 'trace asbestos identified' is used.

SIGNATURE:

PRINT NAME:

Ewelina Kowalczyk Pariyar

Reg. No.2378228 England. Registered Office: Envirochem, 12 The Gardens, Broadcut, Fareham, Hampshire. PO16 8SS.

Page 2 of 3



Shield Environmental Services Ltd
 Surveying Division
 Shield House
 Caxton Business Park
 Crown Way, Warmley
 Bristol BS30 8XJ

Tel 0117 960 6366
 Fax 0117 960 5583
 Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2007 Shield Environmental Services Ltd





ENVIROCHEM

Analytical Laboratories Ltd.

12 The Gardens

Broadcut, Fareham

Hampshire

PO16 8SS



Tel: (01329) 287777

Fax: (01329) 287755

www.envirochem.co.uk

office@envirochem.co.uk

Our Ref: 1205077 FI 18

Your Ref:

Date: 18 June 2012

ASBESTOS FIBRE IDENTIFICATION REPORT

Client: Shield Environmental Services Ltd (Bristol)
 Shield House, Caxton Business Park, Crown Way, Warmley, Bristol, BS30 8XJ
Site address: Regal Theatre, Minehead, The Avenue, TA24 5UQ
Sampled by: Client
Date sampled/received: 15 June 2012
Date analysed: 18 June 2012
Analyst/s: E. Kowalczyk Pariyar

ANALYTICAL PROCEDURE

Fibre identification was carried out in accordance with the documented 'in-house' methods based on the HSE Guidance Note HSG 248. These employed stereo microscopy, polarized microscopy and dispersion staining techniques.

B-50239/014	1205077 14FI	Panel behind plasterboard panel	Yes	Chrysotile
B-50239/015	1205077 15FI	Residues within wall	No	
B-50239/016	1205077 16FI	External. Residues to wall	No	
B-50239/017	1205077 17FI	Roofing felt	Yes	Chrysotile
B-50239/018	1205077 18FI	Residues to external/internal wall to entrance	No	

NOTES:

- 1-Sample(s) were examined for the presence of 6 types of asbestos fibre: crocidolite (blue), amosite (brown), chrysotile (white), anthophyllite, actinolite, and tremolite.
- 2-Samples collected by the client are evaluated using information provided by the client. For samples collected by the client the date of receipt is deemed to be the same as the date sampled.
- 3-Envirochem is a UKAS accredited laboratory for sampling and identification of asbestos containing materials.
- 4-Comments, observations and opinions are outside the scope of UKAS accreditation.
- 5-The analytical method in the HSG248 does not quantify the amount of asbestos present, therefore UKAS accreditation does not permit quantification.
- 6-If, during fibre identification, only 1 or 2 fibres are seen and identified as asbestos, then the term 'trace asbestos identified' is used.

SIGNATURE:

PRINT NAME:

Ewelina Kowalczyk Pariyar

Reg. No.2378228 England. Registered Office: Envirochem, 12 The Gardens, Broadcut, Fareham, Hampshire. PO16 8SS.

Page 3 of 3



212

Shield Environmental Services Ltd
 Surveying Division
 Shield House
 Caxton Business Park
 Crown Way, Warmley
 Bristol BS30 8XJ

Tel 0117 960 6366
 Fax 0117 960 5583
 Email enquiries@shieldenvironmental.co.uk

Report Format © Copyright 2007 Shield Environmental Services Ltd

